

REPLACEMENT SHEET




FIG. 1

REPLACEMENT SHEET

FIG. 2*

FIG. 2*

FleetCross			
SEARCH METHODS FILE EDIT TOOLS HELP			
PARTS & LABOR GENERATOR			
VIN: (ENTER LAST SIX DIGITS):		UNIT NUMBER:	
1FUYSSEB2VLG48309		022352	
MANUFACTURER:			
FREIGHTLINER CORPORATION—FRGHT			
MODEL OR COMPONENT:			
CENTURY CLASS-LOONV CEN DDE			
VEHICLE SYSTEM:			
011001—AXEL-FRONT, NON-DRIVEN			
PARTS APPLICATION DESCRIPTION		REPAIR TIME APPLICATION	
FF-981, S, C1, S31L14A47H46IS		FRONT AXLE KNUCKLE, SPIN	
SPNDL NUT/TRB, RS, S, 4 PC		FRONT AXLE KNUCKLE, STC	
		FRONT AXLE, SCREW	
		400-000578	
PARTS PER APPLICATION DESCRIPTION:			
PART NUMBER	PART DESCRIPTION	PART MFR	
MOTOR OPERATIONS PER APPLICATION DESCRIPTION:			
SRT CODE:	SRT DESCRIPTION		

மே

REPLACEMENT SHEET

FleetCross

SEARCH METHODS

FILE

EDIT

TOOLS

HELP

?

PARTS & LABOR GENERATOR

VIN: (ENTER LAST SIX DIGITS):

UNIT NUMBER:

1FUYSSEB2YLG48309

022352

MANUFACTURER:

FREIGHTLINER CORPORATION--FRGHT

MODEL OR COMPONENT:

CENTURY CLASS-LCONV CEN DDE

VEHICLE SYSTEM:

011001--AXEL-FRONT, NON-DRIVEN

PARTS APPLICATION DESCRIPTION

FF-981, S, G1, S311 14A4746HS

SPNDL NUT/TRB,RS,S4 PC

REPAIR TIME APPLICATION

FRONT AXLE KNUCKLE SPIN

FRONT AXLE KNUCKLE,STC

FRONT AXLE,SCREW

DAMAGE GROUP

400-002541

400-002560

400-000578

PARTS PER APPLICATION DESCRIPTION:

PART NUMBER	PART DESCRIPTION	PART MFR
TDA A3 3111W3377	KNUCKLE ASSY LH	FRGHT
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT
TDA 3101Z1088	PIN-KNUCKLE	FRGHT

LABOR OPERATIONS: PER APPLICATION DESCRIPTION:











SRT CODE:











SRT DESCRIPTION

FIG. 4

FleetCross

SEARCH METHODS FILE EDIT TOOLS HELP





PARTS & LABOR GENERATOR

VIN: (ENTER LAST SIX DIGITS):
1FUYSSB2VLG48309
UNIT NUMBER:
022352
MANUFACTURER:
FREIGHTLINER CORPORATION—FRGHT
MODEL OR COMPONENT:
CENTURY CLASS-LOONV CEN DDE
VEHICLE SYSTEM:
011001—AXEL-FRONT, NON-DRIVEN

PARTS APPLICATION DESCRIPTION	REPAIR TIME APPLICATION	DAMAGE GROUP
FF-981, S, GC1, S3114A4746HS	FRONT AXLE, KNUCKLE, SPIN	400-002541
SPNDL NUT/TRB, RS, S, 4 PC	FRONT AXLE, KNUCKLE, STC	400-002560
	FRONT AXLE, SCREW	400-000578

PARTS PER APPLICATION DESCRIPTION:

PART NUMBER	PART DESCRIPTION	PART MFR
TDA A3 3111W3377	KNUCKLE ASSY LH	FRGHT
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT
TDA 3101Z1088	PIN-KNUCKLE	FRGHT

LABOR OPERATIONS PER APPLICATION DESCRIPTION:

SRT CODE	SPT DESCRIPTION
400-0000	ACTUAL TIME
400-0050A	STEERING KNUCKLE, R/R
400-0050B	STEERING KNUCKLES, 2/R/R

FIG. 5

REPLACEMENT SHEET

FleetCross		SEARCH METHODS		FILE		EDIT		TOOLS		HELP	
<div> </div>											
1000											
WORK SUMMARY NUMBER:				DATE CREATED:				CUSTOMER NAME:			
1000				10/03/2001							
VIN:				UNIT NUMBER:							
1FUYSSB2YL646308				022352							
MANUFACTURER:											
FREIGHTLINER CORPORATION--FRGHT											
MODEL OR COMPONENT:											
CENTURY GLASS-CONV. CEN DDE											
PARTS USED:											
PART MFR		PART NUMBER		PART DESCRIPTION		VMRS CODE		QTY.			
FRGHT		TDA A3 311W3377		KNUCKLE ASSY LH		011001		1			
PFI: (PRIMARY FAILED ITEM):											
PART MFR		PART NUMBER		PART DESCRIPTION		VMRS CODE		QTY.			
LABOR SUMMARY:											
DAMAGE CODE		SRT CODE		SRT DESCRIPTION		VMRS CODE		HOURS			
PRIMARY DAMAGE CODE: CAMPAIGN NUMBER:											
TOTAL HOURS: 0.00											

FIG. 6

REPLACEMENT SHEET

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP
<div> </div>							
1000							
WORK SUMMARY NUMBER:		DATE CREATED:		CUSTOMER NAME:			
1000		10/03/2001					
VIN:		UNIT NUMBER:					
1FUYSSEB2YLG46309		022352					
MANUFACTURER:							
FREIGHTLINER CORPORATION—FRGHT							
MODEL OR COMPONENT:							
CENTURY GLASS-CONV. GEN DDE							
PARTS USED:							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
PFI: (PRIMARY FAILED ITEM):							
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.			
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1			
LABOR SUMMARY:							
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS			
PRIMARY DAMAGE CODE: COMPONENT NUMBER:							
				TOTAL HOURS: 0.00			

FIG. 7

REPAIR DATE
PLEASE ENTER THE REPAIR DATE AS MM/DD/YYYY: THEN PRESS ENTER TO CONTINUE:
09/24/2001
<input type="button" value="CANCEL"/>

FIG. 8

DAMAGE REASON SELECTION	
*SINGLE CLICK THE DAMAGE REASON CODE TO CONTINUE:	
DAMAGE CODE	DESCRIPTION
130	BROKEN
740	WORN
850	LOOSE
<div><input type="button" value="CANCEL"/></div>	

FIG. 9

FIG. 10

FleetCross		<input type="button" value="X"/> <input type="button" value="X"/> <input type="button" value="X"/>	
<div style="display: flex; justify-content: space-between;"> SEARCH METHODS FILE EDIT TOOLS HELP <div style="display: flex; gap: 5px;"> </div> </div>			
WORK SUMMARY NUMBER: <input style="width: 150px;" type="text"/>		CUSTOMER NAME: <input style="width: 150px;" type="text"/>	
VIN: <input style="width: 150px;" type="text"/>		UNIT NUMBER: <input style="width: 150px;" type="text"/>	
MANUFACTURER: <input style="width: 100%;" type="text"/>			
FREIGHTLINER CORPORATION—FRGHT			
MODEL OR COMPONENT: <input style="width: 100%;" type="text"/>			
CENTURY GLASS-LGVN. CEN DDE			
PARTS USED:			
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE QTY.
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001 1
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001 1
PFI: (PRIMARY FAILED ITEM):			
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE QTY.
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001 1
LABOR SUMMARY:			
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE HOURS
400-002541740	400-0050B	STEERING KNUCKLES 2/R/R	011001 5.20
PRIMARY DAMAGE CODE: CAMPAIGN NUMBER: <input style="width: 100px;" type="text"/>			TOTAL HOURS: <input style="width: 100px;" type="text"/>

FleetCross		SEARCH METHODS		FILE		EDIT		TOOLS		HELP																																				
<div>1000</div> <div>WORK SUMMARY NUMBER: 1000 DATE CREATED: 10/03/2001 CUSTOMER NAME:</div> <div>VIN: 1FUYSSB2YLG46309 UNIT NUMBER: 022352</div> <div>MANUFACTURER: FREIGHTLINER CORPORATION—FRGT</div> <div>MODEL OR COMPONENT: CENTURY GLASS-L CONV. CEN DDE</div> <div>PARTS USED:<table border="1"><thead><tr><th>PART MFR</th><th>PART NUMBER</th><th>PART DESCRIPTION</th><th>VMRS CODE</th><th>QTY.</th></tr></thead><tbody><tr><td>FRGHT</td><td>TDA A3 3111W3377</td><td>KNUCKLE ASSY LH</td><td>011001</td><td>1</td></tr><tr><td>FRGHT</td><td>TDA A3 3111T3400</td><td>KNUCKLE ASSY RH</td><td>011001</td><td>1</td></tr></tbody></table></div> <div>PFI: (PRIMARY FAILED ITEM):<table border="1"><thead><tr><th>PART MFR</th><th>PART NUMBER</th><th>PART DESCRIPTION</th><th>VMRS CODE</th><th>QTY.</th></tr></thead><tbody><tr><td>FRGHT</td><td>TDA A3 3111T3400</td><td>KNUCKLE ASSY RH</td><td>011001</td><td>1</td></tr></tbody></table></div> <div>LABOR SUMMARY:<table border="1"><thead><tr><th>DAMAGE CODE</th><th>SRT CODE</th><th>SRT DESCRIPTION</th><th>VMRS CODE</th><th>HOURS</th></tr></thead><tbody><tr><td>400-002541740</td><td>400-0050B</td><td>STEERING KNUCKLES,2,R/R</td><td>011001</td><td>5.20</td></tr></tbody></table></div> <div>PRIMARY DAMAGE CODE: CAMPAIGN NUMBER: TOTAL HOURS: 5.20</div> <div>400-002541740</div>												PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.	FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1	FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1	PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.	FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1	DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS	400-002541740	400-0050B	STEERING KNUCKLES,2,R/R	011001	5.20
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.																																										
FRGHT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1																																										
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1																																										
PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.																																										
FRGHT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1																																										
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS																																										
400-002541740	400-0050B	STEERING KNUCKLES,2,R/R	011001	5.20																																										

FIG. 11

FIG. 12

FleetCross SEARCH METHODS FILE EDIT TOOLS HELP				
	<input type="text" value="1000"/>			
WORK SUMMARY NUMBER: <input type="text" value="1000"/> DATE CREATED: <input type="text" value="10/03/2001"/> CUSTOMER NAME: <input type="text"/>				
VIN: <input type="text" value="1FUYSEB2YL646309"/> UNIT NUMBER: <input type="text" value="022352"/>				
MANUFACTURER: <input type="text" value="FREIGHTLINER CORPORATION—FRGT"/>				
MODEL OR COMPONENT: <input type="text" value="CENTURY GLASS-LCONV. CEN DDE"/>				
PARTS USED:				
PART MFR	PART NUMBER	PART DESCRIPTION	WMRS CODE	QTY.
FRGT	TDA A3 3111W3377	KNUCKLE ASSY LH	011001	1
FRGT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1
PFI: (PRIMARY FAILED ITEM):				
PART MFR	PART NUMBER	PART DESCRIPTION	WMRS CODE	QTY.
FRGT	TDA A3 3111T3400	KNUCKLE ASSY RH	011001	1
LABOR SUMMARY:				
DAMAGE CODE	SRT CODE	SRT DESCRIPTION	WMRS CODE	HOURS
400-002541740	400-0050B	STEERING KNUCKLES,2,R/R	011001	5.20
PRIMARY DAMAGE CODE: CAMPAIGN NUMBER: <input type="text" value="400-002541740"/> TOTAL HOURS: <input type="text" value="5.20"/>				

REPLACEMENT SHEET

SAVE

WORKSUMMARY

1000 WORK SUMMARY

FILE NAME: 022352 09/24/2001 WARRANTY

SAVE AS TYPE: WORK SUMMARY FILES (*.WORK SUMMARY)

☐ OPEN AS READ ONLY

SAVE

CANCEL

FIG. 13

SERIAL NUMBER

PLEASE ENTER THE SERIAL NUMBER TO COMPLETE THE POST TO PARTS & LABOR GENERATOR FUNCTION...

YLG48309|

CANCEL

FIG. 20

FREIGHTLINER QUICKCLAIM

EXCP

DEALER CODE XXXX

022352 09/24/2001	WAR
-------------------	-----

VELOC SYSTEM 1000	MFG CD	SERIAL # (LAST 7)
	FTI	1GY8309

FILE	DISTANCE	DATE FAILED
	85228	09/24/2001

0730	DATE REPAIRED	0012/12/001
B/O #		
1000		0012/12/001

REPLACED DISTANCE	1000
DATE REPLACED	09/24/2001

DISTANCE	8228	DATE RECEIVED	09/24/2001
----------	------	---------------	------------

SRT CODE	HOURS
400-00608	6.2
TOTAL LABOR	260.00

LOCATION	CUSTOMER NAME
XXXXXXXXXX	XXXXXXXXXX

FSDOC#	CUSTOMER PERFORMED REPAIR?	DISTANCE UNITS
	Y	MLEB

	CURRENT	MAJOR COMPONENT	REPLACED
COMPONENT TYPE	<input type="text"/>		
		MODEL #	<input type="text"/>
		SERIAL #	<input type="text"/>

PRIMARY FAILED PART
TDA A3 311172400

PART #	QTY	HHDL	PRICE EA
TDA A3 3111W8377	1	Q30	\$412.50
TDA A3 3111I3400	1	Q33	\$412.30
TOTAL PARTS			\$824.60

DAMAGE CODE	400-002641740
-------------	---------------

COMMENTS

RIGHT KNICKER SEIZED UPON INSPECTION LEFT KNICKER NEAR FAILURE ALSO REPLACED.

CLAIM TOTAL	\$1084.80
-------------	-----------

SUBLET	REFERENCE #	FREIGHT	OTHER	OUTSIDE TOTAL

FIG. 14

FIG. 15

FleetCross	
SEARCH METHODS FILE EDIT TOOLS HELP	
DOCULINK	
VIN: (ENTER LAST SIX DIGITS)	UNIT NUMBER:
<input type="text" value="1FUYSSEB2YL646309"/>	<input type="text" value="022352"/>
MANUFACTURER:	
<input type="text" value="FREIGHTLINER CORPORATION—FRGHT"/>	
MODEL COMPONENT:	
<input type="text" value="CENTURY GLASS-LOCONV. CEN DDE"/>	
PART NUMBER	PART DESCRIPTION
<input type="text" value=""/>	<input type="text" value="PART MFR."/>

IMAGE INFORMATION	
IMAGE NAME	IMAGE DESCRIPTION
400-C10707	FF-881 S,C1 S31L14A47X48HS
297-C03003	FL90.EOF RCPT. TRUCK
771-C05704	FLOOR COV-BAG AREA CRPT/DBL IN
772-C15407	FLOOR COVER 70.MRIRR MATS
120-150083	FLTR-CLNTFG DD80.BLU RL MTD
703-C00953	FLX CONV.AC WIRECRG 1H,BINARY
724-C02208	FLX,C10/C12
170-C02528	FLX.DDC 80.ECR.VALVE
702-C01684	FLX120-CAT 3408.88.BINARY,SAN
156-C01901	FLX-O/I,SRS60.DR450.ETN,70 SC
551-C00204	FRAME FASTENERS,HUCKSPIN
546-C02602	FRAME RAO 1018

REPLACEMENT SHEET

ADOBE ACROBAT - [400_C10707.PDF]									
FILE EDIT DOCUMENT TOOLS PLUG-INS VIEW WINDOW HELP									
PART NUMBER ALT PART NUMBER DESCRIPTION UN QTY CAN BUY									
S10-12641-007			ROXFF982423 C1.831424A47346HS	EA	1	Y			
TDA 3190L7636			BEAM-AXLE,CENTER	EA	1	Y			
TDA A3 3111W3377			KNUCKLE ASSY LE	EA	1	Y			
TDA A3 3111T3400			KNUCKLE ASSY RE	EA	1	Y			
TDA 313347812			ARM-STEERING, LH	EA	1	Y			
TDA 32 3102K4379			TIE-ROD ASST, FF, STRAIGHT	EA	1	Y			
TDA A3102K43779			TIE-ROD	EA	1	Y			
TDA K2414			COTTER	EA	2	Y			
TDA 323701070			EXCITER	EA	2	Y			
TDA 1225P1254			BUSHING	EA	4	Y			
TDA A12052142S			SEAL ASST-OIL	EA	4	Y			
TDA 12258426			BUSHING-ANCHOR PIN	EA	4	Y			
TDA 1226B1236			BUSHING-CAMSHAFT	EA	2	Y			
TDA A1205K2513			SEAL-GREASE	EA	2	Y			
TDA 1199N1850			PITTING-GREASE	EA	2	Y			
TDA 2297N6903			CAP-KING PIN	EA	2	Y			
TDA 3101Z1066			PIN-KNUCKLE	EA	2	Y			
TDA 2203K3001			SHIM, 010	EA	2	Y			
TDA 220343002			SHIM, 005	EA	2	Y			
TDA A120523015			READING-TADJUST	EA	2	Y			

FIG. 16

FIG. 19

<div style="display: flex; justify-content: space-between;"> FleetCross <div> <div style="display: flex; align-items: center;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">-</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">□</div> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;">X</div> </div> <div> <div style="display: flex; justify-content: space-between; width: 100%;"> SEARCH METHODS FILE EDIT TOOLS HELP </div> <div style="display: flex; justify-content: space-between; width: 100%;"> <div style="display: flex; align-items: center;"> </div> <div style="display: flex; align-items: center;"> </div> </div> </div> </div></div>	
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="border: 1px solid black; padding: 5px;"> DIRECT PART NUMBER </div> <div style="border: 1px solid black; padding: 5px;"> FRGHT - FREIGHTLINER CORPORATION </div> </div>	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> PART NUMBER JDA A3 3111T3400 </div> <div style="border: 1px solid black; padding: 5px;"> <div style="display: flex; justify-content: space-between;"> <div> PRIMARY CROSS REFERENCE(S): </div> <div> <div style="border: 1px solid black; padding: 2px; margin-bottom: 2px;"> PART NUMBER (3) PART MFR </div> <div style="border: 1px solid black; padding: 2px; margin-bottom: 2px;"> 400-C10707 FRITBM - FREIGHTLINER BILL OF MATERIAL NUMBER </div> <div style="border: 1px solid black; padding: 2px; margin-bottom: 2px;"> A3 3111T3400 RCKIN - ROCKWELL INTERNATIONAL CORP. (NOW </div> <div style="border: 1px solid black; padding: 2px;"> 011-001 YNPRSK - VEHICLE MAINTENANCE REPORTING STA </div> </div> </div> </div>	<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> SEARCH </div> <div style="border: 1px solid black; padding: 5px; height: 100px;"> VEHICLE SYSTEM </div>
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> PART DESCRIPTION (1) </div> <div style="border: 1px solid black; padding: 5px;"> KNUCKLE ASSY RH </div>	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> APPLICATION DESCRIPTION (1) </div> <div style="border: 1px solid black; padding: 5px;"> FF-981,S,C1.S31L14A47X46HS </div>	

<div style="display: flex; justify-content: space-between;"> FleetCross SEARCH METHODS FILE EDIT TOOLS HELP </div> <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="display: flex; gap: 5px;"> </div> <div style="display: flex; gap: 5px;"> </div> </div>									
<div style="display: flex; justify-content: space-between;"> <div> PARTS & LABOR GENERATOR VIN: (ENTER LAST SIX DIGITS): 1FUYSEB2YL64630 MANUFACTURER: FREIGHTLINER CORPORATION—FRGHT MODEL OR COMPONENT: CENTURY CLASS-LCONV CEN DDE VEHICLE SYSTEM: 011001 - AXLE - FRONT, NON-DRIVEN </div> <div> UNIT NUMBER: 022352 </div> </div>									
PARTS APPLICATION DESCRIPTION FF-981,S,C1 S31L14A47X46HS	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">REPAIR TIME APPLICATION</th> <th style="text-align: left;">DAMAGE GROUP</th> </tr> <tr> <td>FRONT AXLE ARM</td> <td>400-000012</td> </tr> <tr> <td>FRONT AXLE ASSEMBLY</td> <td>400-0000A10</td> </tr> <tr> <td>FRONT AXLE,BEAM</td> <td>400-000085</td> </tr> </table>	REPAIR TIME APPLICATION	DAMAGE GROUP	FRONT AXLE ARM	400-000012	FRONT AXLE ASSEMBLY	400-0000A10	FRONT AXLE,BEAM	400-000085
REPAIR TIME APPLICATION	DAMAGE GROUP								
FRONT AXLE ARM	400-000012								
FRONT AXLE ASSEMBLY	400-0000A10								
FRONT AXLE,BEAM	400-000085								
PARTS PER APPLICATION DESCRIPTION:									
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">PART NUMBER</th> <th style="text-align: left;">PART DESCRIPTION</th> <th style="text-align: left;">PART MFR</th> </tr> <tr> <td>TDA A3 3111T3400</td> <td>KNUCKLE ASSY RH</td> <td>FRGHT</td> </tr> </table>	PART NUMBER	PART DESCRIPTION	PART MFR	TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="height: 40px;"></td> </tr> </table>		
PART NUMBER	PART DESCRIPTION	PART MFR							
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT							
LABOR OPERATIONS PER APPLICATION DESCRIPTION:									
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">SRT CODE</th> <th style="text-align: left;">SRT DESCRIPTION</th> </tr> <tr> <td style="height: 40px;"></td> <td></td> </tr> </table>	SRT CODE	SRT DESCRIPTION			<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="height: 40px;"></td> </tr> </table>				
SRT CODE	SRT DESCRIPTION								

FIG. 21

FleetCross SEARCH METHODS FILE EDIT TOOLS HELP					
	<div style="border: 1px solid black; height: 40px; margin-bottom: 5px;"></div> <div style="float: right; border: 1px solid black; padding: 2px; font-size: small;">SEARCH</div> <div style="clear: both;"></div> <div style="border: 1px solid black; padding: 5px;"> PRIMARY CROSS REFERENCE(S) <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;">PART NUMBER (3)</th> <th>PART MFR</th> </tr> </thead> <tbody> <tr> <td>TDA A3311T3400</td> <td>FRGHT - FREIGHTLINER CORPORATION</td> </tr> </tbody> </table> </div> <div style="border: 1px solid black; padding: 5px;"> PART DESCRIPTION </div> <div style="border: 1px solid black; padding: 5px;"> APPLICATION DESCRIPTION </div>	PART NUMBER (3)	PART MFR	TDA A3311T3400	FRGHT - FREIGHTLINER CORPORATION
PART NUMBER (3)	PART MFR				
TDA A3311T3400	FRGHT - FREIGHTLINER CORPORATION				
<div style="border: 1px solid black; padding: 5px;"> DIRECT PART NUMBER ROCKIN-ROCKWELL INTERNATIONAL CORP. (NON MERITOR) </div> <div style="margin-top: 10px;"> PART NUMBER [A3 3111T3400] </div>	<div style="border: 1px solid black; height: 100px; margin-bottom: 5px;"></div> <div style="float: right; border: 1px solid black; padding: 2px; font-size: small;">VEHICLE SYSTEM</div> <div style="clear: both;"></div>				

FIG. 22

FIG. 23















<div style="display: flex; justify-content: space-between;"> FleetCross SEARCH METHODS FILE EDIT TOOLS HELP </div>										
<div style="display: flex; justify-content: space-around;">               </div>	<div style="border: 1px solid black; padding: 5px;"> <h3 style="margin: 0;">PARTS & LABOR GENERATOR</h3> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div> <p>VIN: (ENTER LAST SIX DIGITS)</p> <p>1FUYSSEB2YL6309</p> </div> <div> <p>UNIT NUMBER:</p> <p>022352</p> </div> </div> <p>MANUFACTURER:</p> <p>FREIGHTLINER CORPORATION—FRGHT</p> <p>MODEL COMPONENT:</p> <p>CENTURY GLASS-LCONV CEN DDE</p> <p>VEHICLE SYSTEM:</p> <p>0111001 - AXLE - FRONT, NON-DRIVEN</p> </div>									
<h3 style="margin: 0;">PARTS APPLICATION DESCRIPTION</h3> <p>FF-981,S,C1.S31L14A47X46HS</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 40%;">REPAIR TIME APPLICATION</th> <th style="width: 40%;">DAMAGE GROUP</th> </tr> <tr> <td>FRONT AXLE, KNUCKLE, SPIN</td> <td>400-002541</td> </tr> <tr> <td>FRONT AXLE, KNUCKLE, STC</td> <td>400-002580</td> </tr> <tr> <td>FRONT AXLE, SCREW</td> <td>400-600578</td> </tr> </table>		REPAIR TIME APPLICATION	DAMAGE GROUP	FRONT AXLE, KNUCKLE, SPIN	400-002541	FRONT AXLE, KNUCKLE, STC	400-002580	FRONT AXLE, SCREW	400-600578
REPAIR TIME APPLICATION	DAMAGE GROUP									
FRONT AXLE, KNUCKLE, SPIN	400-002541									
FRONT AXLE, KNUCKLE, STC	400-002580									
FRONT AXLE, SCREW	400-600578									
<h3 style="margin: 0;">PARTS PER APPLICATION DESCRIPTION:</h3>										
PART NUMBER	PART DESCRIPTION	PART MFR								
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT								
<h3 style="margin: 0;">LABOR OPERATIONS PER APPLICATION DESCRIPTION:</h3>										
SRT CODE	SRT DESCRIPTION									

FIG. 24

FleetCross		SEARCH METHODS		FILE	EDIT	TOOLS	HELP										
<div>DOCULINK</div> <div> <div>VIN: (ENTER LAST SIX DIGITS):</div> <div>1FUYSS2YLG46309</div> </div> <div> <div>UNIT NUMBER:</div> <div>022352</div> </div> <div>MANUFACTURER:</div> <div>FREIGHTLINER CORPORATION —FRGHT</div> <div>MODEL OR COMPONENT:</div> <div>CENTURY CLASS - LCONV CEN DDE</div> <div>VEHICLE SYSTEM:</div> <table border="1"> <tr> <th>PART NUMBER</th> <th>PART DESCRIPTION</th> <th>PART MFR</th> </tr> <tr> <td>TDA A3 3111T3400</td> <td>KNUCKLE ASSY RH</td> <td>FRGHT</td> </tr> </table> <div>IMAGE INFORMATION:</div> <table border="1"> <tr> <th>IMAGE NAME (1)</th> <th>IMAGE DESCRIPTION</th> </tr> <tr> <td>400-C10707</td> <td>FF-981, S, C1.S31LA4447X46HS</td> </tr> </table>								PART NUMBER	PART DESCRIPTION	PART MFR	TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT	IMAGE NAME (1)	IMAGE DESCRIPTION	400-C10707	FF-981, S, C1.S31LA4447X46HS
PART NUMBER	PART DESCRIPTION	PART MFR															
TDA A3 3111T3400	KNUCKLE ASSY RH	FRGHT															
IMAGE NAME (1)	IMAGE DESCRIPTION																
400-C10707	FF-981, S, C1.S31LA4447X46HS																

FIG. 25

PART NUMBER FOOTNOTE				ALT PART NUMBER	DESCRIPTION	UN	QTY	CAN BUY
S10-12541-007					ROXFF982423 C1.831424A47346HS	EA	1	Y
TDA 3190L7636					BEAM-AXLE,CENTER	EA	1	Y
TDA A3 3111W3377					KNUCKLE ASSY LE	EA	1	Y
TDA A3 3111T3400					KNUCKLE ASSY RE	EA	1	Y
TDA 313347812					ARM-STEERING, LH	EA	1	Y
TDA 32 3102K4379					TIE-ROD ASST, FF, STRAIGHT	EA	1	Y
TDA A3102K43779					TIE-ROD	EA	1	Y
TDA K2414					COTTER	EA	2	Y
TDA 323701070					EXCITER	EA	2	Y
TDA 1225P1254					BUSHING	EA	4	Y
TDA A12052142S					SEAL ASST-OIL	EA	4	Y
TDA 12258426					BUSHING-ANCHOR PIN	EA	4	Y
TDA 122651236					BUSHING-CAMSHAFT	EA	2	Y
TDA A1205K2513					SEAL-GREASE	EA	2	Y
TDA 1199N1850					PITTING-GREASE	EA	2	Y
TDA 2297N6903					CAP-KING PIN	EA	2	Y
TDA 3101Z1066					PIN-KNUCKLE	EA	2	Y
TDA 2203K3001					SHIM, 010	EA	2	Y
TDA 220343002					SHIM, 005	EA	2	Y
TDA A122052305					READING, THRUJST	EA	3	Y

RRPLACEMENT SHEET

☐ FleetCross

SEARCH METHODS FILE EDIT TOOLS HELP

☐ 1000

WORK SUMMARY NUMBERS: DATE CREATED: CUSTOMER NAME:

1000 09/25/2001

VIN: UNIT NUMBER:

1HTSCAAM9WH555971 178

MANUFACTURER:

INTERNATIONAL - NVSTR

MODEL OR COMPONENT:

4700 4X2

PARTS USED:

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.
NVSTR	200818DC93	PUMP, POWER STRNG	015005	1

PFI (PRIMARY FAILED ITEM)

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.

LABOR SUMMARY:

DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS
05000-701 K	A05-191	POWER STEERING PUMP R/R	015005	1.50

PRIMARY DAMAGED CODE: CAMPAIGN MEMBER: TOTAL HOURS: 1.50

05000-701 K

FIG. 26

REPLACEMENT SHEET

☐ FleetCross

SEARCH METHODS FILE EDIT TOOLS HELP

1000

WORK SUMMARY NUMBERS: DATE CREATED: CUSTOMER NAME:
1000 10/03/2001
VIN: UNIT NUMBER:
854778 158-0714
MANUFACTURER:
VOLVO TRUCKS NORTH AMERICAQ - VLVNA
MODEL OR COMPONENT:
WG84
PARTS USED:

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.
VLVNA	8022509	CONDENSER, A/C	001001	1

PFI (PRIMARY FAILED ITEM)

PART MFR	PART NUMBER	PART DESCRIPTION	VMRS CODE	QTY.

LABOR SUMMARY:

DAMAGE CODE	SRT CODE	SRT DESCRIPTION	VMRS CODE	HOURS
NONE	67401500	CONDENSER, REPL. INCL. R&R GRILLE	001001	1.50

PRIMARY DAMAGED CODE: CAMPAIGN MEMBER: TOTAL HOURS: 1.50
NONE

FIG. 27